HIL Limited CUSTOMER COMPLAINT WALL PUTTY COMPENSATION REPORT

Dated:25/11/2021

Complaint Details:								
Sales Representative:	JUHIL MODI(50003499)	Compensation Number:45468	Complaint Tracking Number :100149					
Complaint Registered Date:	21/11/2021	Complaint Attended Date:	24/11/2021					
Party Name:	Aasha Trading Co.(1130611)	Location:	Gota Gujarat					
Material Supplied From:		Product:	Wall Putty Manufacture/Traded					
Invoice Number and Date:	(2032003671,12/11/2021)							
Product Details:	(Birla Aerocon Putty - Project (40 KG))							

Breakage Investigation Details:							
Invoice No	Invoice Date	Product Details	PP	Defect Quantity	Transnortor		Actual Defect Quantity
2032003671	12/11/2021	Birla Aerocon Putty - Project (40 KG)	125	11	super bharat roadways	0.8	1
Remarks For Any Special Approvals:							

Compensation Recommendation:

Based on the above inspection details, please supply to the above party (Wall Putty Manufacture/Traded) (1) numbers (in words): (ONE) or (0.04) of following size

Recommended Size	Recommended Quantity(No's)		
Birla Aerocon Putty - Project (40 KG)	1		

or issue the credit note for the above mentioned quantity of material based on the above invoice price and considering below mentioned sales recommendations.

Reviewed By

Approved By

Avinash KHATRE QUALITY ASSURANCE

Dated:25/11/2021

I K PANDIT

HEAD-QUALITY ASSURANCE

Dated:25/11/2021

Comments/Approval from Sales:

Based on the above, credit amount of to be issued to the above customer.

Name of the person:

Head Sales:

Signature:

Any Special Remarks:

version 3 dated 14.01.12