## HIL Limited CUSTOMER COMPLAINT WALL PUTTY COMPENSATION REPORT

Dated:26/12/2022

Complaint Details:						
Sales Representative:	Ankur Pandey(50003924)	Compensation Number:59574	Complaint Tracking Number :122272			
Complaint Registered Date:	14/11/2022	Complaint Attended Date:	09/12/2022			
Party Name:	Jeevish Sales Corporation(1125702)	Location:	GORAKHPUR Uttar Pradesh			
Material Supplied From:		Product:	Wall Putty Manufacture/Traded			
Invoice Number and Date:	(2031014239,19/09/2022)					
Product Details:	(BIRLA HIL PUTTY 40 KG (001))					

Breakage Investigation Details:							
Invoice No	Date	Product Details	Quantity	Defect Quantity	Transporter	Defect %	Actual Defect Quantity
2031014239	19/09/2022	BIRLA HIL PUTTY 40 KG (001)	875	11()	In order to business	1.14	10
Remarks For Any Special Approvals:							

## Compensation Recommendation:

Based on the above inspection details, please supply to the above party (Wall Putty Manufacture/Traded) (10) numbers (in words): (TEN) or (0.4) of following size

Recommended Size	Recommended Quantity(No's)
BIRLA HIL PUTTY 40 KG (001)	10

or issue the credit note for the above mentioned quantity of material based on the above invoice price and considering below mentioned sales recommendations.

Reviewed By	Approved By			
Avinash KHATRE QUALITY ASSURANCE Dated:20/12/2022	I K PANDIT HEAD-QUALITY ASSURANCE Dated:20/12/2022			
Comments/Approval from Sales:				
Based on the above, credit amount of to be issued to the above customer.				
Name of the person:				
Head Sales:				
Signature:				
Any Special Remarks:				
	version 3 dated 14.01.12			