HIL Limited CUSTOMER COMPLAINT BREAKAGE COMPENSATION REPORT

Dated:28/03/2019

Complaint Details:							
Sales Representative:	Shrishail Turke(50000522)	Compensation Number:14366	Complaint Tracking Number :51672				
Complaint Registered Date:	18/05/2018	Complaint Attended Date:	04/06/2018				
Party Name:	PREFAB INFRAPROJECTS PVT. LTD(1110844)	Location:	NAGAPUR - Maharashtra				
Material Supplied From:	Thimmapur Plant	Product:	Panel				
Number and	(2008009749,09/05/2018)-(2008009751,09/05/2018)-(2008009750,09/05/2018)-(2008009216,27/03/2018)-(2008009217,27/03/2018)-(2008009218,27/03/2018)-(2008009276,30/03/2018)-(2008009280,30/03/2018)-(2008009509,17/04/2018)						
	(Aerocon Panel (SE) 50 x 600 x 3000 MM),(Aerocon Panex x 3000 MM)	el (RE) 75 X 600 X 2400 MM),(Aerocon Panel (RE) 75 x 600				

Breakage Investigation Details:							
Supplied Quantity (No's)	Total Breakage Quantity (No's)	Transporter	1Kreakanec	U \ 1	Actual Breakage Quantity In No's (after excluding 3% Breakage Qty)		
1275	134	Geosafe Carriers	10.51	0	134		
Remarks For Any Special Approvals:							

Compensation Recommendation:

Based on the above inspection details, please supply to the above party (Panel) (134) numbers (in words): (ONE HUNDRED THIRTY FOUR) or (11.7141) Metric Tons of following size

Recommended Size	Recommended Quantity(No's)
Aerocon Panel (RE) 75 x 600 x 3000 MM	11
AEROCON PANEL (RE) 75 X 600 X 2400 MM	118
Aerocon Panel (SE) 50 x 600 x 3000 MM	5

or issue the credit note for the above mentioned quantity of material based on the above invoice price and considering below mentioned sales recommendations.

Reviewed By	Approved By	
Avinash KHATRE QUALITY ASSURANCE Dated:06/06/2018	I K PANDIT HEAD-QUALITY ASSURANCE Dated:06/06/2018	
Comments/Approval from Sales:		_

Based on the above, credit amount of to be issued to the above customer.

Name of the person:

Head Sales - Panels/Blocks/Hysil/Drymix Products:

Signature:

Any Special Remarks:

version 3 dated 14.01.12