

CAR Information

CAR Number	PSC-2026-004	Status	Draft
Vessel	—	Target Date	16 Feb 2026
Inspection Type	PSC	Inspection Date	09 Feb 2026
Port	Singapore	Created	09 Feb 2026 06:38

Deficiency Details

Deficiency Code	07106
Description	Fire detection system in engine room found inoperative. Smoke detectors in zone 3 not responding during test.
Action Code	16
Cleared	No

Root Cause Analysis

No CLC codes assigned.

Root Cause Summary:

Not provided.

Corrective Actions

No corrective actions recorded.

Evidence

No evidence uploaded.

Review / Approval History

Date	Event	Performed By
09 Feb 2026 06:38	CAR PSC-2026-004 created for deficiency 07106	John Smith