

MAINTENANCE & INSPECTION LOG

Equipment: Valve V-88 (Pressure Relief Valve, Zone B)

Facility: Reference Industrial Plant

Entry: Near-Miss Follow-up Inspection

Date: 2026-07-14

Inspector: N. Rao (Shift Lead)

Findings: Fourth seepage event at the same seal location on Valve V-88 since March 2025. Seal replaced again. This continues the pattern first noted by V. Menon in November 2025, where the same seal interface has now failed on four separate occasions across approximately sixteen months. Recommend escalating the seal replacement interval review that was previously suggested but not formally scheduled.

Governing Standards: OISD-STD-105, Factory Act 1948 Chapter IV