

NEAR-MISS REPORT

Report No: NM-2026-0058

Facility: Reference Spice Plant, Grinding Department

Date: 2026-07-18

Reported by: Grinding Shift Team, filed by M. Reddy (Grinding Section Engineer)

Description: Dust accumulation observed once again at the UPZ Line feeding point, the same location flagged in June 2025 and March 2026. This is now the third documented occurrence at this exact feeding point in just over a year.

Immediate Action: Area cleared. The ventilation review first recommended thirteen months ago has still not been completed.

Note from reporting officer: Three occurrences at the same feeding point, with the second involving a nearby ignition source, should no longer be treated as isolated near-misses. This is a systemic ventilation gap at this specific point on the UPZ Line that requires a permanent engineering fix, not repeated housekeeping response.

Classification: Near-miss, combustible dust accumulation - grinding feed point, recurring, third occurrence.