Test Execution Report

EXEC-00098 — Status: FAIL

1. Execution Summary

Execution ID	EXEC-00098
Status	FAIL
Build Version	5.1.6
Timestamp	2023-11-19 04:50:35
Duration	69 seconds (69475 ms)
Executed By	eng009@synthetic-qa.dev
Test Run	RUN-005 — Regression Cycle 5 — Build 5.1.6
Release	REL-006 — 5.2.7
Environment	ENV-008 — Production-like

2. Test Case Reference

Test Case ID	TC-0055
Title	Test that user authentication correctly handles invalid input when the user revo...
Test Type	Performance
Priority	Medium
Automation	Manual
Requirement	REQ-0442 — UI Behavior — Session Token Refresh

3. Environment Details

Environment ID	ENV-008
Name	Production-like
Device Type	Mobile
OS Version	One UI 6.0
Network Type	5G
Location	Seoul Lab
Configuration	4-core CPU, 8GB RAM, 81GB storage

4. Executed Steps

1	Initiate AR scene rendering by pressing the 'Start' button.	The UI transitions to the next screen within 3 seconds.	PASS
2	Launch the DigitalWallet application on the test device.	A success toast message is displayed.	PASS

SYNTHETIC DATA — No real Samsung confidential information

3	Initiate NFC tap-to-pay by pressing the 'Sync' button.	The fallback UI is displayed with a human-readable error message.	PASS
4	Launch the VoiceAssistant application on the test device.	The audit log records the event with correct metadata.	FAIL

5. Failure Details

Failure ID	FAIL-0020
Failure Type	Crash
Severity	Major
Component	Sensor Manager
Error Message	Process com.samsung.smarthome terminated unexpectedly with signal SIGSEGV (segmentation fault).
Observed	The system exhibited crash when the user revokes permissions during the operation.
Expected	The system should complete NFC tap-to-pay within the defined SLA.
Resolution	Resolved

Error Log Excerpt:

```
com.samsung.browser.Authentication.execute(line 725)
```

6. Synthetic Data Notice

This document is entirely synthetic and intended for AI/RAG research only.