Test Case Specification

TC-0384 — Ensure firmware over-the-air update synchronizes correctly across devi...

1. Test Case Identity

Test Case ID	TC-0384
Title	Ensure firmware over-the-air update synchronizes correctly across devices when t...
Type	Integration
Priority	Critical
Severity	Major
Automation Status	Manual
Estimated Duration	576 seconds
Status	Draft
Created By	ENG-017 — Wendy Kim

2. Application & Requirement

Application ID	APP-008
Application	VoiceAssistant
Domain	AI
Suite ID	TS-0106
Requirement ID	REQ-0197
Req Title	Functional — Crash Reporting
Req Type	UI Behavior
Req Priority	Low

3. Test Environment

Environment ID	ENV-005
Environment	Infra Lab
Device Type	Cloud Node
OS Version	Ubuntu 22.04
Network Type	Ethernet
Location	Bangalore Lab

4. Objective

Confirm that the feature behaves correctly under the session token has expired.

5. Preconditions

Device is enrolled, firmware >= 5.2.0, network profile set to low-bandwidth.

SYNTHETIC DATA — No real Samsung confidential information

6. Test Steps

1	Launch the DigitalWallet application on the test device.	The performance counter logs a value below the SLA threshold.	payload_size=1KB
2	Observe the status indicator for up to 27 seconds.	Server returns HTTP 200 with a valid JSON payload.	N/A
3	Enter valid credentials: username='testuser_035', password='[REDACTED]...	A success toast message is displayed.	network_profile=low-bandwidth
4	Record response time using the built-in performance monitor.	The UI transitions to the next screen within 3 seconds.	device_id=DEVICE-565

7. Description & Objective Detail

Confirm that the system recovers gracefully after Data Mismatch during background sync.

8. Recent Execution History

EXEC-03171	2024-07-24 19:15	PASS	6.0.9	ENV-004	27s

11. Synthetic Data Notice

This document is entirely synthetic and intended for AI/RAG research only.

SYNTHETIC DATA — No real Samsung confidential information