Test Case Specification

TC-1471 — Validate that NFC tap-to-pay returns the correct result when two concu...

1. Test Case Identity

Test Case ID	TC-1471
Title	Validate that NFC tap-to-pay returns the correct result when two concurrent requ...
Type	Performance
Priority	Medium
Severity	Critical
Automation Status	Manual
Estimated Duration	175 seconds
Status	Draft
Created By	ENG-014 — Fiona Chen

2. Application & Requirement

Application ID	APP-011
Application	ConnectedDevices
Domain	IoT
Suite ID	TS-0108
Requirement ID	REQ-0516
Req Title	UI Behavior — Offline Mode
Req Type	Connectivity
Req Priority	High

3. Test Environment

Environment ID	ENV-006
Environment	Cloud Test Env
Device Type	Cloud Node
OS Version	Ubuntu 22.04
Network Type	Ethernet
Location	Seoul Lab

4. Objective

Confirm that the feature behaves correctly under the target device is running a legacy firmware version.

5. Preconditions

Device is enrolled, firmware >= 5.3.0, network profile set to stress-test.

SYNTHETIC DATA — No real Samsung confidential information

6. Test Steps

1	Re-connect the wearable and confirm auto-recovery.	The fallback UI is displayed with a human-readable error message.	username=testuser_030
2	Launch the DigitalWallet application on the test device.	The device reconnects automatically within 10 seconds.	network_profile=degraded-netwo...
3	Check server logs for event code 'EVT-3856'.	The device reconnects automatically within 10 seconds.	retry_count=2
4	Capture a screenshot and attach as evidence.	A success toast message is displayed.	payload_size=1KB
5	Check server logs for event code 'EVT-9006'.	The operation completes without error.	network_profile=high-load
6	Enter valid credentials: username='testuser_033', password='[REDACTED]...	The audit log records the event with correct metadata.	payload_size=1KB

7. Description & Objective Detail

Confirm that diagnostics report generation triggers the expected notification when the target device is running a legacy firmware version.

8. Recent Execution History

EXEC-03853	2024-08-27 22:34	NOT_RUN	6.2.3	ENV-009	75s
EXEC-00744	2024-01-21 09:41	FAIL	5.3.1	ENV-005	100s
EXEC-02791	2024-01-19 20:09	SKIPPED	6.0.9	ENV-007	65s

9. Associated Failures

FAIL-0163	UI Failure	Major	ElementNotFoundError: XPath '//button[@id='pair']' not ...

10. Associated Defects

BUG-0078	UI Failure in Rendering Engine: ElementNotFoundError: X...	Major	IN_PROGRESS

11. Synthetic Data Notice

This document is entirely synthetic and intended for AI/RAG research only.

SYNTHETIC DATA — No real Samsung confidential information