Test Case Specification

TC-1551 — Validate that NFC tap-to-pay enforces access control when the target d...

1. Test Case Identity

Test Case ID	TC-1551
Title	Validate that NFC tap-to-pay enforces access control when the target device is r...
Type	Regression
Priority	High
Severity	Minor
Automation Status	Manual
Estimated Duration	1112 seconds
Status	Active
Created By	ENG-056 — Helen Evans

2. Application & Requirement

Application ID	APP-006
Application	XRPlatform
Domain	XR
Suite ID	TS-0053
Requirement ID	REQ-0356
Req Title	Connectivity — Health Metric Upload
Req Type	Security
Req Priority	Low

3. Test Environment

Environment ID	ENV-003
Environment	Hub Lab
Device Type	Hub
OS Version	Tizen 7.0
Network Type	WiFi-6
Location	Cloud-GCP

4. Objective

Confirm that the feature behaves correctly under the input data contains Unicode special characters.

5. Preconditions

Device is enrolled, firmware >= 5.2.0, network profile set to low-bandwidth.

SYNTHETIC DATA — No real Samsung confidential information

6. Test Steps

1	Observe the status indicator for up to 27 seconds.	The audit log records the event with correct metadata.	device_id=DEVICE-966
2	Disconnect the hub and wait 23 seconds.	The audit log records the event with correct metadata.	payload_size=1KB
3	Disconnect the wearable and wait 22 seconds.	The operation completes without error.	N/A
4	Initiate playlist shuffle by pressing the 'Connect' button.	The UI transitions to the next screen within 3 seconds.	retry_count=3
5	Disconnect the hub and wait 13 seconds.	The fallback UI is displayed with a human-readable error message.	device_id=DEVICE-593
6	Observe the status indicator for up to 15 seconds.	A success toast message is displayed.	N/A

7. Description & Objective Detail

Test that media streaming correctly handles invalid input when two concurrent requests are made simultaneously.

8. Recent Execution History

EXEC-00768	2024-09-20 06:25	FAIL	7.0.4	ENV-008	119s
EXEC-03323	2024-05-13 23:50	PASS	6.0.9	ENV-007	80s
EXEC-04244	2024-02-07 18:08	PASS	4.3.2	ENV-007	36s

9. Associated Failures

FAIL-0143	Network Failure	Major	SocketException: Connection reset by peer on interface ...
FAIL-0167	Configuration Error	Minor	ConfigError: missing required key 'SIGNING_KEY' in envi...

10. Associated Defects

BUG-0051	Configuration Error in Payment Gateway: ConfigError: mi...	Minor	VERIFIED

11. Synthetic Data Notice

This document is entirely synthetic and intended for AI/RAG research only.

SYNTHETIC DATA — No real Samsung confidential information