This is a guide describing all of the steps being used in the JEX workflow.

1 Import CTC Images From NIS Folder

This imports the raw image files in .nd2 format