Zebra DS457 Barcode Scanner Configuration Procedure

Scan each of the following barcodes in sequence to prepare the scanner for use with the the Cinder-BarcodeScanner block. Unplug and replug the scanner at the end of the procedure.

1.

Set Factory Defaults

2.

SSI over USB CDC

3.

Disable ACK/NAK (0)