



IFAD MOTORS LTD Head Office

DAS DONE

IFAD TOWER ,07 Tejgaon I/A, Dhaka-1208.


F.R SI NO# 231

Ref.No: June-231			F.R SI NO#	231	Date:	23.06.2020					
Zone Name:	Zone Name: Cumilla			Engineer Name:		Md.Pabel Sarker					
Approved by: Prabir Biswas, GM -Head of Service & Spare Parts.											
Customar Name:	Abdul Gufor				Mobile No:	01319271651					
Address:	Kuti-Chowh	moni, Kosba, B. B	aria.		Dealer Name:	Modina Motors					
Customar Complain:-		CH NO Full #	MD6M14CA5K4K00452			Present Kms #	3,450				
Rear shock absorber has right		EN NO Full#	AK4KK4809549			Model#	Tvs King Deluxe				
oil leakage and nose.		Sale Date #	16.02.2020				lpg				
		Date of Comp#	25.03.2020			1St PS Date	1st PS Kms				
		Date of Repair #	25.03.2020				1				
		Free service information									
		1St Free Service		2nd Free Service		3rd Free Service					
		Date	KMs	Date	KMs	Date	KMs				
		25.03.2020	1100	23.06 <i>,2</i> 020	3450						
Obserbation:- we checked &found that Rear Shock Absorber has right oil leakage & nose.											
Action Taken:- Require to replace this parts under warranty for approval.											

Failure Particular										
SL	Part NO	Part Name	Qty)	Vendor code	Approved	Rejected				
1	G2090100	Rear Shock Absorber	01	Gabrial						
2		×								
3						2,				
4				a a feet						
5										
6		2								

Failure Parts Photo

For Head Office Use



012/2020