TVS

PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD Head Office

OMS JOB NO 2724

1st PS Kms

15t PS Date

IFAD TOWER ,07 Tejgaon I/A, Dhako-1208. 29.10.2020 Date: F.R SI NO# 326 Ref.No: Habiganj/Oct/326 Md. Abdullah Al Zabed **Engineer Name:** Zone Name: Habiganj Zone Approved by: Prabir Biswas (Head of Service & Spare Parts) 01776047819,01754951636 Mobile No: Mst. Rukshana Begum Customar Name: Shahjalal Automobile Dealer Name: Olipur , Habiganj Address: 2430 Present Kms# MD6M14CA7J4A07902 CH NO Full # Customar Complain:vs King Deluxe Ak4AJ4822726 Front Shock absorber has broken. EN NO Full # Model # NGHEPG 06.09.2020 Sale Date #

28.10.2020

 Date of Repair #
 28.10.2020
 Free service information

 15t Free Service
 2nd Free Service
 3rd Free Service

 Date
 KMs
 Date
 KMs
 Date
 KMs

 30.09.2020
 940
 28.10.2020
 2430
 430
 430

Obserbation:- we checked & found that front Shock absorber has broken.

Date of Comp#

Action Taken:- New one front shock absorber replaced.

		Failure	Particular		sad wite i	1
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected
	G4100180	Front shock absorber		Gabrial (60000297)-	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
1			0	03/01/18H	stuaic	4
2		The state of the s			- and year	- 6
3			1		MANAGE S	
4						
5		1			- 35 P.	
6						

Failure Parts Photo

For Head Office Use

m182020

Mohammad Abdullah Al Zahed Senior Service Engineer IFAD MOTORS LTD. Cell: 01701-227974 McMilon Hossain
Sr. Service Engineer (Trainer)
IFAD Motors I td

ONS Complete Nitubahar 01/11/2020