

PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD Head Office

DMS JOB NO

2310

IFAD TOWER, 07 Tejgaon I/A, Dhako-1208.

Ref.No:	Habiganj/August/317	F.R SI NO#	317	Date:	20.08.2020
Zone Name:	Habiganj Zone	Eı	ngineer Name:	Md. Abdul	llah Al Zabed

Approved by: Prabir Biswas (Head of Service & Spare Parts)

Customar Name:	Md. Monsur Miah			Mobile No:	01724154757 / 01726661115			
Address:	Shrimonggol, Moulvibaz	onggol, Moulvibazar			Kaderia Motors			
Customar Compla	nin:- CH NO Full #	NO Full # MD6M14CL1K4NAQ017		Present Kms #	172			
Poor pick -up	EN NO Full #	0L4NK40A0017			Model #	TVS KING		
	Sale Date #	18.08.202	20	1.55 %	iviouei #	DURAMAX CNG		
Date of Comp#		20.08.2020		1St PS Date	1st PS Kms			
	Date of Repair #	20.08.202	20					
а		Free service information						
	1St Free Se	1St Free Service 2nd Fre		ee Service	3rd Free Service			
	Date	KMs	Date	KMs	Date	KMs		
	20.08.2020	172						
Obserbation: We ch	ecked & found that IGNIT	TON COLL V	MAC MEAR		· · · · · · · · · · · · · · · · · · ·			

Action Taken:- New one IGNITION COIL WITH SUP. CAP 4S replaced.

Failure Particular							
SL		Pårt NO	Part Name	Qty-	Vendor code	Approved	Rejected
1		G4060370	IGNITION COIL WITH SUP. CA	1	NIG011909A01		
2		+ G4060250	11	Y1)			
3				V.my	Dux		
4				.,,,,			
5					** ** *** *		
6		* 8					

Failure Parts Photo

For Head Office Use

Replaced from a new vehicle 8 pares already in Withstehen be fitted Dry 5 Complete Vehicle

02/0/2020.