

## PRODUCT PERFORMANCE FEEDBACK REPORT





## IFAD MOTORS LTD **Head Office**

DMS JOB NO 21055

IFAD TOWER ,07 Tejgaon I/A, Dhaka-1208.

	07 Toi	agon I/A. DI	haka-1208.		
	IFAD TOWER ,07 Tej	guon 1770 21	310	Date:	28.07.2020
	-0	F.R SI NO#	310	na L Abdu	llah Al Zabed
Ref.No: Hak	oiganj/July/310	Eng	gineer Name:	Ma. Abdu	man Ar Zana
Zone Name: Ha	biganj Zone				
Zorie Haine	bir Biswas (Head of Service & Spa	ire Parts)			
Approved by Fra	Dit Dice (		- 1:1- N/4	01791222300	5
		N.	Mobile No:	017322	1 11-


A removed by:	Prabir Bi	iswas (Head of Serv	ice a span		, t		
Approved by:					Mobile No:	01791222300	
I IISLOIIIai Isaiiis.		nak Miah			Dealer Name:	Shahjalal Aotumobile Present Kms # 2650	
Customar Compla	ain:-	CH NO Full #	MD6M14C AK4AJ4722	A0J4A07949 1992	9/	Model #	TVS KING DELUXE CNG
Front Shock absorbe broken.	Sale Date #		07.06.2020 28.07.2020		1St PS Date	1st PS Kms	
		Date of Repair #	28.07.202	0 Free se	ervice information	on	- Corvice
1St Free Serv			e 2nd Free Service		3rd Fro	ee Service KMs	
		<b>Date</b> 28.07.2020	<b>KMs</b> 2650	Date	1/.		
1			al - ale abcor	her has bro	кел.		

Obserbation:- we checked & found that Front Shock absorber has broken.

Action Taken:- New one Front Shock absorber replaced.

						d
		Failure	Particular		Approved	Rejected
	Part NO	Part Name	Oty	Vendor code Gabrial (600002	Approved	
SL 1	G2100010	Front shock absorbe		Gabrial (53		192 <sup>8</sup> 12
2					2 N	
3					-	
4						
5	*					
6			<del></del>	For He	ead Office Use	

**Failure Parts Photo** 



For Head Office Use

mgnas 4/8/2020

04/8/20201