Ix. 2269 7640



PRODUCT PERFORMANCE FEEDBACK REPORT



IFAD MOTORS LTD Head Office

DMS JOB NO

rieda Ojjice						2272
	IFAD TOWER	,07 Tejga	on I/A, D	haka-12	08.	
Ref.No:	Cumilla/Factory -01		F.R SI NO	01	Date:	31.03.21
Zone Name: Joydebpur			Engineer Name: Md.Neyamat Ullah			
Approved by:	PRABIR BISWES,GM- H	EAD OFSERV	ICE & SPAR	E PARTS		
Customar Name:	IFAD MOTORS LTD,			Production	<u> </u>	
Address:				Eng. Mobile	017101-204620	
Assembler Complain:- CH NO Full #		MD6M14C	MD6M14CL5L4N00110		Present Kms #	20
Self Start Problem	EN NO Full #	0L4NL4900277		Model#	TVS KING	
	Production Date #	22.03.2021	22.03.2021 22.03.2021			Duramax Plus
	PDI Date #	22.03.2021				CNG
Date of Repair				, i		
Action Taken:-Requ	uired this parts relpceme	nt under wa	rranty for y	our kind ap	pproval.	
* 2		Failure Pa	rticular	4		-570
SL Part N	O Part Nar	ne	Qty	MRP	Approved	Rejected
1 G40601	70 Satrter Mo	otor	1			8
2					,	0)
		4			600/10	100
					111/10/0	
						T
	ailure Parts Photo			For F	lead Office Use	

Doys complete.