PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD

DMS NO:

Head Office

IFAD Tower, Plot-7(New), Tejgoan Industrial Area	, Dhaka-1208
--	--------------

Ref.No: Sunamgonj/Dec/27/39	F.R SI NO	F.R SI NO 39	Date:	27.12.2021
			Dute.	27.12.2021

Zone Name: Sunamgonj Engineer Name: Tisu Barua Mchanic Name: Md. Moin Uddin

Approved by: Kaushhik Sarkar-COO(IFAD GROUP)

	T						
Customer Name:	Afiya Begum				Mobile No:	01737-857	904
Address:	Sunamgonj Sador, Sunamgonj.			Dealer Name	M/S Sohe	l Enterprise	
Customer Complain:- CH NO Full # MI				Present Kms # 8231			
Oil leakage from fr	ont shock	t shock EN NO Full # AK4BM4401613		3			
absorber		Sale Date #	12.09.2021			Model #	TVS King Deluxe plus
		Date of Comp#	12.12.2021		1St PS Date	1st PS Kms	
		Date of Repair#					
		Free service information					
		1St Free Service 2nd Fre		ee Service	3rd Free Service		
		Date	KMs	Date	KMs	Date	KMs
Obsarbation, 144	28.09.2021	1012	25.10.21	3,423	27.11.2021	6354	


Obserbation:- We checked & found that oil leakege front shock absorber.

Action Taken:- Require to replace this parts under warranty for your approval.

Failure Particular

	T						
SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected	-
1	G4100180	Front shock absorber	1 .	Gabrial			
2							
3							-
4							

E-Maria Barria B	
Failure Parts Photo	F
· andre rares riloto	For Head Office Use
	Tol field Office Ose



Head of Service

Engineer

DMS

Approved by Mithe Schar Nall Drib Complete