

## PRODUCT PERFORMANCE FEEDBACK REPORT





## IFAD MOTORS LTD Head Office

DMS JOB NO

7-Tejgoan Industrial Area, Ifad Tower Level-01, Dhaka-1208

Ref.No:	Noakhali- nov- 235			F.R SI NO#	235	Date:	05.11.20		
Zone Name:	<u> </u>			Engineer Name:		Kazi Samiul Hoque			
	1	was, GM -Head of	Service &	Spare Parts.					
					Mobile No:	01887898270			
Customar Name:	Rashida be	gum			+ /				
Address:	Kaliyapara	,chadpur.	dpur. Dealer Name:				Bhuiya motors		
Customar Complain:-		CH NO Full #	MD6M14CA8K4K00056		6	Present Kms #	4500		
Rear shockabsorber oil leakage		EN NO Full #	AK4KK4602922		Model #	Tvs King Deluxe cng			
		Sale Date #	16.08.20						
		Date of Comp#	04.11.20		1St PS Date	1st PS Kms			
		Date of Repair #	04.11.20						
		Free service information							
		1St Free Service 3		2nd Fi	ree Service	3rd Free Service			
		Date	KMs	Date	KMs	Date	KMs		
		12.10.20	3500	04.11.20	4500				
Obserbation:- We	checked &	found that rear sho	ckabsorb	er oil leakage.					
			<b>√</b>		A Mary May				

Action Taken:- Please Replaced the following parts under warranty

SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected
1	G2090100	Rear shockabsorber	( 1 )	Gabrial		
2				a expedit en la company		
3			1. 1.	augus provide a construction de la construction de	1 8 100 1 5 1 5 1 5 1 5	
4				NAME OF THE PARTY		
5			, A 104 x 400 1	hind Proprietation incomes a second		
6			20-21-5	The Company of the State of the	N N N N N N N N N N N N N N N N N N N	

**Failure Parts Photo** 

For Head Office Use

07.11.20

21/11/2020

Drys Complete Netweshow ~ 11/11/2020