TVS >=	PRODU	PRODUCT PERFORMANCE FEEDBACK REPORT					TVS	
	·	IFΔD	MOT	TORS LTD	The second secon		DMS NO:	
MOTORSU	imited			Office			3397	
	1545 7				wiel Aven Dhe	les 1200	3004	
		er, Plot-7(New), rejg				06 42 2024	
Ref.I	No: October - 295			F.R SI NO#	296	Date:	06.12.2021	
Zone Name: Cumilla/ B.Baria				Engineer Name: Md.Pabel Sarker		Mchanic Nam	Mchanic Name: Sumon Dali	
	by: Prabir Biswas (Head	d of Service,Spare F	arts &	Production)	1			
					T			
Customer Name Sarmin Akhter				Mobile No:	+88013108	+8801310816663		
Address: Burichong, Cumilla		\$.			Dealer Name:	Bismillah '	Bismillah TVS CNG Motors	
Customer Co	omplain:-	CH NO Full # MD6M14CL3K4P002			238	Present Km	Present Km 20451	
ngine crank	case Broken.	EN NO Full #		4200554		─ Model#	TVS King Duramax	
		Sale Date #	09.12.					
		Date of Comp#	23.10.	2021		1St PS Date	1st PS Kms	
		Date of Repair#		· • • • • • • • • • • • • • • • • • • •	anniac informati	ion		
		4Ct Fuer Com	Free service information 1St Free Service 2nd Free Service 3rd Free Service					
		Date	KMs	Date	KMs	Date	KMs	
				Date	IXIVIS .	Dute		
ve checked	:- &found that conecting n:- Require to replace th	09.01.2021	2561 chambe	for approval.		15.07.2021 on assly scratch	1	
ve checked	&found that conecting	09.01.2021	2561 chambe	er broken & Cy	rlinder block pisto	on assly scratch	1.	
ve checked	&found that conecting	09.01.2021 rod , Engine main nose parts under w Part Nam	2561 chambe arranty Failure e	er broken & Cy for approval. Particular Qty	vlinder block pisto			
ve checked Action Taker	&found that conecting n:- Require to replace the Part NO. G4020180	09.01.2021 rod , Engine main nose parts under w Part Nam crankshaft a	2561 chambe arranty Failure e	er broken & Cy for approval. Particular Qty	rlinder block pisto	on assly scratch	1.	
SL 1	Require to replace the Part NO. G4020180 G4322970	09.01.2021 rod , Engine main nose parts under w Part Nam crankshaft a piston	2561 chamber arranty Failure e	er broken & Cy for approval. Particular Qty 01 02	vlinder block pisto	on assly scratch	1.	
Ne checked Action Taker SL 1	Require to replace the Part NO. G4020180 G4322970 G4011470	o9.01.2021 rod , Engine main nose parts under w Part Nam crankshaft a piston cylinder BLC	2561 chambe arranty Failure e assy	Particular Qty 01 02 1	vlinder block pisto	on assly scratch	1.	
SL 1 2 3 4	Part NO. G4020180 G4021470 G4011350	Part Nam crankshaft a piston cylinder BLC gaskit cly. H	chamber arranty Failure e esssy	er broken & Cy for approval. Particular Qty 01 02 1	vlinder block pisto	on assly scratch	1.	
SL 1 2 3 4 5 5	Part NO. G4020180 G4011470 G4011420	Part Nam crankshaft a piston cylinder BLC gaskit cly. H gaskit cly. Bl	2561 chamber arranty Failure e assy OCK ead ock	Particular Oty 01 02 1 1 2	vlinder block pisto	on assly scratch	1.	
SL 1 2 3 4 5 6	Part NO. G4020180 G4322970 G4011470 G4011420 G4030030	Part Nam crankshaft a piston cylinder BLC gaskit cly. H gaskit cly. Bl crackcase	2561 chamber arranty Failure e assy OCK ead ock	Particular Oty 01 02 1 1 2	vlinder block pisto	on assly scratch	1.	
SL 1 2 3 4 5 5	Part NO. G4020180 G4011470 G4011420	Part Nam crankshaft a piston cylinder BLC gaskit cly. H gaskit cly. Bl	2561 chamber arranty Failure e assy OCK ead ock	Particular Oty 01 02 1 1 2	vlinder block pisto	on assly scratch	1.	
SL 1 2 3 4 5 6 7	## Require to replace the repl	Part Nam crankshaft a piston cylinder BLC gaskit cly. H gaskit cly. Bl crackcase	2561 chamber arranty Failure e assy OCK ead ock	er broken & Cy for approval. Particular Oty 01 02 1 1 2 1 01	Vendor code FOC	Approved	1.	
SL 1 2 3 4 5 6 7	Part NO. G4020180 G4322970 G4011470 G4011420 G4030030	Part Nam crankshaft a piston cylinder BLC gaskit cly. H gaskit cly. Bl crackcase crackcase Lh	2561 chambe arranty Failure e assy OCK ead ock rh	Particular Oty 01 02 1 1 2 1 01 05	Vendor code FOC r Head Office Use	Approved	Rejected	
SL 1 2 3 4 5 6 7	## Require to replace the repl	Part Nam crankshaft a piston cylinder BLC gaskit cly. H gaskit cly. Bl crackcase crackcase Lh	2561 chamber arranty Failure e assy OCK ead ock	Particular Oty 01 02 1 1 2 1 01 05	Vendor code FOC	Approved	1.	