PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: 3325 **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 26.06.21 Date: 72 F.R SI NO# Ref.No: Mym-72 Mchanic Name:Md Anamul Haq Engineer Name:Md Jahid Hasan Zone Name: Mymenshingh Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) 1778170811 Mobile No: Fajlur rahman **Customer Name:** Rai Enterprise Dealer Name: Netrokona Address: 6392 Present Km MD6M14CA5K4L00132 CH NO Full # **Customer Complain:-**TVS King Dyramax Ak4LK4106695 EN NO Full # Model# Engine oil consumpsion 21.09.2020 Sale Date # 1st PS Kms 1St PS Date 17.06.21 Date of Comp# N/A N/A 22.06.21 Date of Repair# Free service information **3rd Free Service 2nd Free Service 1St Free Service KMs** Date **KMs KMs** Date Date 4927 30.12.20 2,981 21.11.20 08.10.20 891 Observation:- we find and checked that engine oil consumpsion (per 120-140 km engine of consumpsion 200 gm). Action Taken:- Please to be replace the piston kit 1s O/S 4s & Engine valve kit by new one under warranty. Failure Particular Approved Rejected Vendor code **Qty** Part Name Part NO. SL piston kit 1st O/S 4s 1 G4320670 1 1 Engine valve kit G4320780 2 3 4 For Head Office Use Failure Parts Photo DMS Engineer **Head of Service**