

PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD Head Office



IFAD TOWER ,07 Tejgaon I/A, Dhako-1208.

Ref.No:	Habiganj/Oct/323	F.R SI NO#	323	Date:	05.10.2020	
Zone Name:	Habiganj Zone	Eng	Engineer Name:		Md. Abdullah Al Zabed	
Approved by	Brahir Ricwas (Hoad of Son	ica & Spara Parts)				

Approved by: Prabir Biswas (Head of Service & Spare Parts)

		÷					
Customar Name:	Md. N	I. Mahmud Miah Mobile No: rputi, Cunarugat, Habiganj Dealer Name:			Mobile No:	01778563134	
Address:	Norpu				Shahjalal Au	tomobile	
Customar Comp	olain:-	CH NO Full #	MD6M14	CA3J4A06844		Present Kms #	2170
Front Shock absorber has		EN NO Full #	AK4AJ4713600		Model #	Tvs King Deluxe	
broken.		Sale Date #	10.08.202	20	NOW T	IVIOGEI #	CNG/LPG
		Date of Comp#	05.10.202	20		1St PS Date	1st PS Kms
		Date of Repair #	05.10.202	20			e e
*		Free service information					
		1St Free Ser	St Free Service 2nd Fr		ee Service 3rd Free Service		e Service
		Date	KMs	Date	KMs	Date	KMs
		01.09.2020	930	05.10.2020	2170	= 10	

Obserbation:- we checked & found that front Shock absorber has broken.

Action Taken:- New one front shock absorber replaced.

		Failu	e Particular	is and great reposition at all the		1 3,
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected
-	1	,		Gabrial		uti
	- G2100010	Front shock absorber		(60006291)	10 m	ų.
1 /			(A) (B)	02 2 17 H		
2	64100180			AND A	1 2	
3	للليه		1.7			

Failure Parts Photo

118720

For Head Office Use

1177

Moi Managa

The signature

Milisaha 14:16:200 Dry S. Complete