

## PRODUCT PERFORMANCE FEEDBACK REPORT





## IFAD MOTORS LTD Head Office

DMS JOB NO

IFAD TOWER ,07 Tejgaon I/A, Dhaka-1208.

, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,											
	Moulvibazar/July/307			F.R SI NO#	307	Date:	19.07.20				
Zone Name: Moulvibazar				Engineer Name:		Md Abdullah AL Zabed					
Approved by: Prabir Biswas (Head of Service & Spare Parts)											
provided from New Zalabad Enterprise											
Customar Name:	Md. Junayed Miah Mobile No					01726630295					
Address:	Moulvib	oazar	8	New Zalabad Enterprise							
Customar Complain:-		CH NO Full #	MD6M14CAXJ4D02153			Present Kms #	2845				
Rear brake drum has been		EN NO Full #	AK4DJ4714800			Model #	Tvs King Deluxe				
broken		Sale Date #	30.05.2020				CNG/LPG				
		Date of Comp#	19.07.20			1St PS Date	1st PS Kms				
		Date of Repair #	19.07.20								
		Free service information									
		1St Free Service		2nd Free Service		3rd Free Service					
		Date	KMs	Date	KMs	Date	KMs				
28.06.2020		985	19.07.2020	2845							
Obserbation:- we checked & found that brake drum has been broken											
ii .			/ [		•	-					


Action Taken:- New one brake drum replace.

Failure Particular\_

Failure Particular										
SL	Part NO	Part Name	Qty	Vendor cod	Approved	Rejected				
11	G2110390	BRAKĘ DRUM	1 / 1	200180		Rejected				
2		A		200100						
3										
4										
5				*		-				
6	A. A.									
				197 800 1		1				

Failure Parts Photo

For Head Office Use



Manaras 20/7/2020

Mitasaka 19.07.200