

PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD Head Office

	89,Bir							
	Ref.No:	IML/lal/Au	ıg/2020/08/25		F.R SI NO#	08	Date:	25/08/2020
Z	Zone Name:	The second secon			E	Engineer Name: Md.Kayem Uddin		
			vas (Head of Servi	se ,S/Parts8	R Production)			
			e =	1				
Customar Name: Pervin Begur			um 🦠 -		Mobile No:	01316021273		
Address: Rangpur		1 - · · · · · · · · · · · · · · · · · ·			Dealer Name:	Antu moni motors (lalmonirhat)		
Customar Complain:-			CH NO Full #	MD6M14CA9K4N00060				
Shockabsorber Assy Rear is		EN NO Full #	AK4LK461	0756				
Damage. (Right side)		Sale Date #	11.06.2020		P	Present Kms #	(4560	
		Date of Comp#	16.08.202) 🗸		Model #	TVS KING	
		Date of Repair #				Iviouei #	Deluxe	
					Free Cupon	service information	tion	
			1St Free Service		2nd Free Service		3rd Free Service	
			Date	KMs	Date	KMs	Date	KMs
×			29/06/20	395 ~	16/08/20	4560	2 0 0 0 0 0	
Obcork	hation: \Me	checked t	he vehicles and fou	ind that She	ockabsorber	is damage, Becau	use of hydrolic sy	ystem is not
				00		100		_
So It p	patrs is chan	ge under w	arranty.	- 0 () -		- N		78 · *
Soltp			arranty.	Failure	Particular	a service of the serv		A *
So It p		>	arranty. Part Nai		Particular Qty	Vendor code	Approved	Rejected
		NO		me	Qty	Vendor code	Approved	Rejected
SL	Part	NO	Part Na	me	Qty		Approved	Rejected
SL 1	Part	NO	Part Na	me	Qty		Approved	Rejected
SL 1 2	Part	NO	Part Na	me	Qty		Approved	Rejected
SL 1 2 3	Part	NO	Part Na	me	Qty		Approved	Rejected
SL 1 2 3 4	Part	NO	Part Na	me	Qty		Approved	Rejected
SL 1 2 3 4 5	Part	NO	Part Na	me	Qty	TVS		Rejected
SL 1 2 3 4 5	Part	NO 0100	Part Na	me	Qty	TVS	Approved	Rejected
SL 1 2 3 4 5	Part	NO 0100	Part Nai Shockabsorber	me	Qty	For Hea		