


PRODUCT PERFORMANCE FEEDBACK REPORT



DMS JOB NO

IFAD TOWER .07 Telagon I/A, Dhaka-1208.

		II AD I OVEL	,0,,9	, 0, 0, 1, 1, 1, -						
Ref.No:	Svlhet/Nov	ylhet/Nov/08/288		F.R SI NO#	288	Date:	08.11.2020			
	Sylhet ,Sadar			Eı	ngineer Name:	Tisu Barua				
		was, GM -Head of S	Service & S	pare Parts.						
					g 15 15 1					
Customar Name:	mar Name: Soltan Ahmed				Mobile No: 💲	01301772876				
Address:	Companygo	onj, Sylhet.	Dealer Name			Tawsis Motors				
Customar Complain:-		CH NO Full #	MD6M14CA6K4K00461			Present Kms #	12,870			
Oil leakege from Front shock		EN NO Full #	AK4KK4209861			Model#	Tvs King Deluxe			
absorber		Sale Date #	04.06.2020				lpg			
		Date of Comp#	07.11.2020			1St PS Date	1st PS Kms			
		Date of Repair #	Pending			No	No			
		Free service information								
		1St Free Service 2nd Fr			ee Service	3rd Free Service				
		Date	KMs	Date	KMs	Date	KMs			
		29.06.2020	865	01.08.2020	3263	30.08.2020	4532			
Obserbation: We	chacked & f	ound that front sh	ock absort	er hard		- 1 1	1			

What is mean

Action Taken:- Require to replace this parts under warranty for your approval

Failure Particular									
SL	Part NO	Part Name	aty	Vendor code	Approved	Rejected			
1	G4100180	Front shock absorber	1	Gabrial					
2		Ø		i i i i i i i i i i i i i i i i i i i					
3									
4									
5									
6				Assemble -	a to a				

Failure Parts Photo

For Head Office Use




表:11:2020

TISU BARUA Service Engineer -AD MOTORS LTD Sylhet Sadar, Sylhet. Hob: 01704-113328

DMS Complete