

PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD Head Office

DMS JOB NO

IFAD Tower,7 Tajgoan Industrial Area, Dhaka-1208

ref.no:	IML /Natore	e/Jan/31/01/2021,	/27	F.R SI NO#	27	Date:	31.01.2021			
Zone Name:	Natore			Engineer Name:		MD.Shohanul Islam				
Approved by:	Prabir Biswas(General Manager)									
					128					
Customar Name:	Md.Sento A	hmed			Mobile No:	01719614473				
Address:	Noldanga,N	atore			Dealer Name:	Friends Trading, Natore				
Customar Complain:-		CH NO Full #	MD6M14CL2K4P00148		Present Kms #	7600				
Fronts site noise, &		EN NO Full #	OL4PK4400370			Model #	Tvs King Duramax			
Shock Absorbers front is not		Sale Date #	20.10.2020			Wiodel #				
working. 7777		Date of Comp#	29.01.2021			1St PS Date	1st PS Kms			
	(Date of Repair #					8			
		Free service information								
		1St Free Service 2nd Fr		ee Service	3rd Free Service					
		Date	KMs	Date	KMs	Date	KMs			
4	a °	30.12.2020	990		-					
Obserbation:- We	checked the	Vehicle and found	that Sho	ck Absorber F	ront is defective	.So it should be	replace undre			

Obserbation:- We checked the Vehicle and found that Shock Absorber Front is defective . So it should be replace undre warranty. From Snock Absorber Del Leakage.

		Failure	Particular			
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected
1	G2100010	Shock absorber assy Fr	01			
2			* /			
3						
4						
5						
		•				

For Head Office Use

MitiSahar 03.00.00.00 DM3 Complete

