

PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD Head Office

DMS JOB NO

	IFAD Tower,7 Tajgoan	Industrial Are	a, Dhako	r-1208	
ref.no:	IML /Natore/April /22/04/2021/29	F.R SI NO#	29	Date:	22.04.2021
Zone Name:	Natore	Engineer Name:		MD.Shohanul Islam	
Approved by:	Prabir Biswas(General Manager)				

Customar Name:	Mst.Mousu	me Begum	enterioristica enterioristica en el contro presentante enterioristica enterioristica en		Mobile No:	01935822854		
Address:	Noldanga,N	latore	RECOMMENDED EXPANSIONS FOR PROPERTY STATES	unicipaliti i Bashi i Burushi di Chinay wasa in 1944 'Ayyu e Tay Dunicipal di Asserti	Dealer Name:	Friends Trac	ling, Natore –	
Customar Co	mplain:-	CH NO Full #	MD6M14	CA5K4KA014	1	Present Kms #	9800	
		EN NO Full #	AK4KK46A0141			Model#	Tvs King Deluxe	
and Leaning to one side.	Sale Date #	30.11.2020						
		Date of Comp#	15.03.21			1St PS Date	1st PS Kms	
		Date of Repair #						
		Free service information						
		1St Free Service 2nd I		2nd Fr	ee Service	3rd Free Service		
		Date	KMs	Date	KMs	Date	KMs	
		07.01.2021	4000	15.03,2021	7000			

Obserbation:- We checked the Vehicle and found that Shock Absorber Rear is oil leakage & defective .

Action Taken: It should be replace undre warranty.

		, Failure	Particular		200 April 1970 - 200 Ap	
SL	Part NO	Part Name	ety	Vendor code	Approved	Rejected
1	G2090100	Shock absorber assy rear	/ 01 /			
2		(7)				
3		- V	-			
4						
5						
		2				

For Head Office Use



100000 A

O Hithraper

Blyn