

## PRODUCT PERFORMANCE FEEDBACK REPORT



## IFAD MOTORS LTD **Head Office**

DMS JOB NO

1820

7-Tejgoan Industrial Area, Ifad Tower, Level-01, Dhaka-1208.

F.R SI NO# Ref.No: Noakhali- Dec- 239 239 Date: 01.12.20 Zone Name: Feni-Noakhali. **Engineer Name:** Kazi Samiul Hoque Prabir Biswas, GM -Head of Service & Spare Parts. Approved by:

01884124074 Customar Name: Saleha begum Mobile No:

Bhuiya motors Address: Kaliyapara, chadpur. Dealer Name:

Present Kms # Customar Complain:-CH NO Full # MD6M14CAXK4L00191 Tvs King Deluxe Front & Rear shockabsorber EN NO Full # AK4LK4706873

Model # cng oil leakage Sale Date # 10.09.20 1St PS Date 1st PS Kms Date of Comp# 29.11.20 Date of Repair # 29.11.20

Free service information

3rd Free Service 1St Free Service 2nd Free Service **KMs** Date Date KMS Date **KMs** 1820 02.10.20 988 29.11.20

Obserbation:- We checked & found that front & rear shockabsorber oil leakage.

Action Taken:- Please Replaced the following parts under warranty

SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected
1	G2090100	Rear shockabsorber	1	Gabrial		
2	G <del>4100180 -</del>	Front shockabsorber	1	Gabrial		
5	G 21000	٥٦				
6						

Failure Parts Photo

For Head Office Use

of loodsage