

Action Taken:- Require to replace this parts under warranty for your approval.

Failure Particular							
SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected	
1	G4011370	Valve Intake	1		**		
2	G4011380	Valve Exhaust	1				
3	G4011100	Valve Stem Oil Seal	2				Ç.
4	G4011470	CYLINDER	1				
5	G4010070	GASKET CYLINDER	1				
6	G4011350	GASKET CYL HEAD	1				

Failure Parts Photo	For Head Office Use				
	Head of Service	Engineer	DMS		
	The state of the s	Media on	String of the st		