PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: 3400 **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 F.R SI NO# 90 Date: 18.12.21 Ref.No: Tan-90 Engineer Name: Md Jahid Hasan Mchanic Name: Md Rofiqul Islam Zone Name: Mymensingh Approved by: Kaushik Sarker (Head of Service -IML) 01775577211 Customer Name: | Md Ripon Mia Mobile No: Mama vagina Engineering Address: Tangail sadar Dealer Name: MD6M14C#L8J4H00091 KSehen Customer Complain:-CH NO Full # Present Kms # 0L4GJ4100152 Engine oil consumption (200 ml EN NO Full # TVS King Model# Duramax225cc Sale Date # 17.03.21 per 100 kms run) 1St PS Date Date of Comp# 15.12.21 1st PS Kms Date of Repair# | Pending N/A N/A Free service information **3rd Free Service** 1St Free Service 2nd Free Service Date **KMs** Date Date **KMs** 17.04.20 1005 30.06.21 2,892 04.09.21 5191 Observation:-.we checked & found that this vehicle Cylinder head & cylinder block piston assly scratch & damage. Action Taken:- Please to be replace the cylinder head assly, Gasket cylinder head, gasket cylinder block, piston by new one under warranty. **Failure Particular** Part NO. SL Part Name Qty Vendor code Approved Rejected 1 G4011300 Cylinder head assly **TVS** 2 G4011350 Gasket cyl. head 1 TÝS 3 G4011420 **Gasket Cylinder** 1 **TVS** kit Piston 6650 G4322980 1 TVS For Head Office Use Failure Parts Photo **Head of Service DMS** Engineer

Dy. Manager (Service) IFAD MOTORS LTD Head Office, Dhaka.