PRODUCT PERFORMANCE FEEDBACK REPORT DMS NO: IFAD MOTORS LTD **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 18/3/2021 Date: F.R SI NO#-325 Ref.No: Engineer Name: Md Farhad Ho Mchanic Name: Momin Zone Name: Chittagong-chokoria Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) Recevied person:- Rofiqul Islam 01885763562 Mobile No: Customer Name: Amran Abu sama Motors Dealer Name: Chokoria Address: 850 Kms# MD6M14CA2J4D02728 CH NO Full # Customer Complain:-Tvs King Deluxe AK4DJ4016848 EN NO Full # Model# Noise from Rear side. 10-Mar-21 Sale Date # 1st PS Kms 1St PS Date 18/3/2021 Date of Comp# Date of Repair# | 18/3/2021 Free service information **3rd Free Service** 2nd Free Service 1St Free Service **KMs** Date **KMs** Date **KMs** Date Observation:- Rear shockabsorber oil leakage Action Taken:- New one rear shockabsorber replace Failure Particular Approved Rejected Vendor code Part Name Qty Part NO. SL vadve SHOCK ABSORBER ASSY, REAR G2090100 1 2 3 4 For Head Office Use **Failure Parts Photo** DMS Engineer Head of Service Mills of the or of old

OMS complete