

PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD Head Office

DMS JOB NO 2106 W

IFAD TOWER,07 Tejgaon I/A, Dhaka-1208.

	Ref.No:	Habiganj/July/309	F.R SI NO#	309	Date:	28.07.2020		
-	Zone Name:	Habiganj Zone	Engineer Name:		Md. Abdullah Al Zabed			
	Approved by:	Prabir Biswas (Head of Service & Spa	re Parts)	6				

Customar Name:	Mst. Ja	mila Khatun			Mobile No:	01738055013	
Address:	Surabo	i, Habiganj Shadar			Dealer Name:	Shahjalal Aotumobile	
Customar Complain:-		CH NO Full #	MD6M14	CA2J4A06883	Í	Present Kms #	1050
Front Shock absorber has		EN NO Full #	AK4AJ4613609 /		Model #	TVS KING DELUXE	
broken.		Sale Date #	07.07.202	.O.		CNG	
		Date of Comp#	28.07.202	:0		1St PS Date	1st PS Kms
		Date of Repair #	28.07.202	.0			Y
		Free service information					
		1St Free Service 2nd Fr		ee Service	3rd Free Service		
J		Date	KMs	Date	KMs	Date	KMs
		28.07.2020	1050		100		


Obserbation:- we checked & found that Front Shock absorber has broken.

Action Taken:- New one Front Shock absorber replaced.

Failure Particular								
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected		
1	G2100010	Front shock absorbe	(1	Gabrial (600002				
2	5		A					
3				¥				
4								
5								
6		/						

Failure Parts Photo

For Head Office Use



monas 4/8/2020

04/08/2020

Ors complete Nituralus