PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: 3204 **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 F.R SI NO# 04.03.2021 21 Date: Ref.No: Dhaka/Feb/21 Engineer Name: Milon Hossain Mchanic Name: Md.Yousuf Zone Name: Dhaka 1 Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) Mobile No: 01942-038643 Customer Name: Md.Shariful Islam Mayer Dowa Workshop Dealer Name: Sirajdikhan, Munshiganj Address: 1042 MD6M14CA2J4L09546 Present Kms **Customer Complain:-**CH NO Full # EN NO Full # AK4LJ4093823 Pickup Problem Model# TVS King Deluxe 27.01.2021 Sale Date # 15.02.2021 Date of Comp# 1St PS Date 1st PS Kms Date of Repair# Free service information **1St Free Service** 2nd Free Service **3rd Free Service** Date **KMs KMs** Date **KMs** Date 988 12.02.2021 Observation:we checked &found that Valve Kit Bend. Action Taken:- Require to replace this parts under warranty for approxal. **Failure Particular** Vendor code Approved Rejected SL Part NO. Part Name Qty **VALVE INTAKE** 1 M7010270

VALVE EXHAUST

VALVE STEM OIL SEAL

2

3

M7010280

N4011100

Failure Parts Photo	For Head Office Use		
	Head of Service	Engineer	DMS
	100 10 1 10 2 1 1 1 1 1 1 1 1 1 1 1 1 1	04/00/2002	Short Short

1

1