

PRODUCT PERFORMANCE FEEDBACK REPORT

Wigsold Co





IFAD MOTORS LTD Head Office

DMS JOB NO

IFAD TOWER,07 Tejgaon I/A, Dhako-1208.

F.R SI NO#	322	Date:	05.10.2020
Engineer Name:		Md. Abdullah Al Zabed	
		2 C1 Var.	2

Approved by: Prabir Biswas (Head of Service & Spare Parts)

Customar Name:	Mst. S	Sufiya katun			Mob	ile No:	01776224183		
Address:	Mirpu	ur bazar, Bahuble, Habiganj			Deal	er Name:	Shahjalal Automobile		
Customar Complain:- CH		CH NO Full #	MD6M14	CA7J4A0679	7	and the second s	Present Kms #	7430	
Front Shock absorber has		EN NO Full #	AK4AJ46	L3489	Model #		Tvs King Deluxe		
broken.		Sale Date #	14.07.202	20		- ()*(-)	iviodei #	CNG/LPG	
		Date of Comp#	04.10.202	20 /			1St PS Date	1st PS Kms	
		Date of Repair #	04.10.202	20			8		
		Free service information							
		1St Free Service 2nd Fre		ree Service		3rd Free Service			
		Date	KMs	Date		KMs	Date	KMs	
		09.08.2020	890	17.09.2020		3140	04.10.2020	7430	

Obserbation:- we checked & found that front Shock absorber has broken.


Action Taken:- New one front shock absorber replaced.

		Failur	e Particular	do terror to the terror	3.	. 3.
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected
				Gabrial		
	-G2100010	Front shock absorber	(01)	(60000297)		
1 /				27.11.17 H	y 1	
P. S	G 4100180			to an a destroyers	9 9	E E
3	ell			16		2 2
4				1 sto 4 >		
				No. of the second	4	

Failure Parts Photo

For Head Office Use

Park Cons



misnas 19/10/2020

13/10/2020

Mitheather 18.10,2020 plete