PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: Head Office IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 05 Ref.No: 66 F.R SI NO# 66 Zone Name: Pabna Date: 12/26/2021 Engineer Name: Md Rakibul Islam Approved by: Mchanic Name: Md Ripon Mollah KAUSHIK BARKAR PAD HROOD Customer Name: | MD RAFIQUL ISLAM Address: Mobile No: VILL.GOPALPUR. P.O.EKDONTO. P.S.ATGHORIYA. DIST.PABNA Dealer Name: 01717-492445 Customer Complain:-Bhai Bhai Motors CH NO Full # MD6M14CLXK4P00172 Vehicle Not starting. Engine coolant Present Kms EN NO Full # 42055 0L4PK4000512 going inside the engine. Sale Date # 02/12/2000 Duramax Model# Date of Comp# 12/26/2021 1St PS Date Date of Repair# 1st PS Kms 9/13/2021 Free service information 28000 1St Free Service 2nd Free Service 3rd Free Service Date KMs/ Date **KMs** 1/12/2021 Date Observation:- Internal coolant leak duo to cylinder head coolant passage hole corroded. The way head gasket seal leak coolant into cylinder and into the crankcase. already Two time head gasket replaced for the coolant leak. Action Taken:- Need to change Cylinder Head. Failure Particular SL Part NO. Part Name 1 G4011300 Qty Vendor code Cyl Head Assy Approved Rejected 2 G4011350 1 TVS NO Gasket Cyl head 3 G4011420 1 **TVS** NK Gasket cyl Block G4020130 1 TVS OK Piston kit STD LC **TVS** OK **Failure Parts Photo** For Head Office Use **Head of Service** Engineer **DMS**