		CTPERFOR			O, IOIX IXE		
FAC		IFAD	MOT	ORS LTD)		
	Head Office						DMS NO:
	IFAD Tower.	Plot-7(New),	Tolac	22 10-1-1			0262
Ref.N	o: Cox's Bazar/April/25	(03	relgo			ika-1208	
				F.R SI NO	# 03	Date:	25.04.2021
20ne Nam	e: Cox's Bazar,Sada	r		Engineer Nar	me:Kanchan das	Mchanic Nan	ne:Al-amin
Approved b	y: Prabir Biswas (Head o	of Service, Spare Pa	arts & P	roduction)			
istomer Name:	Shajan						,
dress:	Cox's Bazar ,sadar				Mobile No:	018780850	001
stomer Compli	ain:-	Tours	T	The second secon	Dealer Name:	Sha Mot	ors
	ock absorber oil leakage	CH NO Full #		M14CA8J4DC	12832	Present Kn	ns 2,850
	on reakage	EN NO Full #		14617044		Model#	Tvs King Delu
		Date of Comp#	The second second	And the same of th		wiodel #	lpg
		Date of Repair#	09.04.	.2021		1St PS Date	1st PS Kms
		- are of Repair#	1	7,		No	No
		1St Free Serv	ico		service informa	tion	
		Date	KMs		ree Service	3rd	Free Service
		26.03.2023	000	Date 11.04.021	KMs	Date	KMs
	checked & found that Replace this parts under w			ber oil leaka	1/96 ,	¥	
on Taken:- re	place this parts under w	varranty for your a		ber oil leaka	ge .	1.	
on Taken:- re	place this parts under w	varranty for your a Fail Part Name	approva	ber oil leaka	ge . Vendor code	Approved	Rejected
on Taken:- re	place this parts under w	varranty for your a	approva	ber oil leaka		Approved	Rejected
	place this parts under w	Part Name Rear Shock Abso	approva	ber oil leaka		Approved	Rejected
on Taken:- re	place this parts under w	varranty for your a Fail Part Name	approva	ber oil leaka		Approved	Rejected
	place this parts under w	Part Name Rear Shock Abso	approva	ber oil leaka		Approved	Rejected
on Taken:- re	place this parts under w	Part Name Rear Shock Abso	approva	al. Qty 1	Vendor code		Rejected
on Taken:- re	Part NO. G2090100	Part Name Rear Shock Abso	approvi	ber oil leaka	Vendor code Head Office Use		Rejected
ion Taken:- re	Parts Photo	Part Name Rear Shock Abso	approvi	ber oil leaka	Vendor code		Rejected
on Taken:- re	Parts Photo	Part Name Rear Shock Abso	approvi	ber oil leaka	Vendor code Head Office Use		
ion Taken:- re	Parts Photo	Part Name Rear Shock Abso	approvi	ber oil leaka	Vendor code Head Office Use		DMS
ion Taken:- re	Parts Photo	Part Name Rear Shock Abso	approvi	ber oil leaka	Vendor code Head Office Use		

OMS Complete