

## PRODUCT PERFORMANCE FEEDBACK REPORT





## IFAD MOTORS LTD Head Office

R338

IFAD TOWER ,07 Tejgaon I/A, Dhaka-1208.

- (1)	Habirani/August/212	F.R SI NO#	313	Date:	06.08.2020	
	e: Habiganj/August/313 e: Habiganj Zone	Er	Engineer Name:		Md. Abdullah Al Zabed	
Zone Name	y: Prabir Biswas (Head of Service					
Approved to	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		1 14 14	04744204920	-	
Customar Name:	Md. Rasel Miah		IVIODITE ITE.	01741284830		
Address:	Kulaura, Moulvibazar		Dealer Name:	A.J Motors	2580	

	W.Janua Maulyibazar		Dealer Name:	A.J MOLOIS	
Address:	Kulaura, Moulvibazar	1		Present Kms #	2580
Customar Compla	ain:- CH NO Full #	MD6M14CA0J4C0090	9		TVS KING DELUXE
Oil out of front shoc		AK4CJ4209017 /		Model #	CNG
200	Sale Date #	11.06.2020		F 4 9	
absorber	Date of Comp#	06.08.2020		1St PS Date	1st PS Kms
	Date of Repair #	06.08.2020			
		Free se	rvice information	n	
	15t Free Som	vice 2nd Fr	ee Service	3rd Fre	e Service
	1St Free Ser	vice Zila i i	· (%)	Data	KMs


1St Free Service		2nd Free Service		3rd Free Service	
Date	KMs	Date	KMs	Date	KMs
19.07.2020	985	06.08.2020	2580		

Obserbation:- we checked & found that Oil out of front shock absorber

Action Taken:- New one Front Shock absorber replaced.

		Failu	re Particular	. Sive 25 - 15		* -
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected
JL	Tareno			Gabrial	0 A A	
	G2100010	Front shock absorbe	(1)	(60000297)	* ***	
1 62100010	Troncon and and		02.02.17 H			
2		A				
3						
4				a to the		
5						

Failure Parts Photo For Head Office Use



monas 14/9/2020

10/8/2020,

ONS complete