

PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD Head Office

IFAD Tower,7 Tajgoan Industrial Area, Dhaka-1208

ref.no:	IML/Chapi	/Oct-17.10.2010		F. D. C. N. C. W.			
Zone Name:	Rajshahi			F.R SI NO#	41	Date:	17.10.2020
Approved by:		was (Head of serv	Engineer Name:			Safayet Hossain	
	1	was (nead of serv	ice)				
Customar Name:	Raju						
Address: Chapainawabganj					Mobile No:	01793-788709	
Customar Complain:-		CH NO Full #	Dealer Name:			Koria Transport Agency	
Noise in the back and the car			MD6M14CA8K4L00187			Present Kms #	2500
tilts to one side when taking a turn.		EN NO Full #	AK4LK4805776 17.08.2020			Model #	
							Tvs King Deluxe
		Date of Comp#	17.10.1020			10	CNG/LPG
		Date of Repair #		_		1St PS Date	1st PS Kms
¥		•		Free ser	vice informatio		
		1St Free Service		2nd Free Service			
		Date	KMs	(Mc D.		3rd Free Service	
		20.09.20	1045		KMs	Date	KMs
Obserbation:- We on turn.So it sould be	observed the	e car and when it f	ell on the r	oad it made	a had'		
i turn.So it sould be	reples und	er Warranty		oud, it made	a nad uoise and	it tilted to one s	ide when taking

a turn.So it sould be reples under Warranty.

Action Taken: Replace the defective parts.

SL	Part NO	Part Name				
1	G2090100		Qty	Vendor code	Approved	Rejected
2	02030100	Shock absorber Rear	1	-		Rejected
3						2
4						
5						
	旗				1	
						•



For Head Office Use

mm 2020