392

## PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: **Head Office** 3339 IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 Ref.No: Mym-78 F.R SI NO# 78 Date: 03.08.21 Engineer Name:Md Jahid Hasan Mchanic Name: Md Forhad Mia Zone Name: Mymenshingh Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) 1743542040 Mobile No: **Customer Name:** Md Sadekur Cecuya, Mymenshingh **Dealer Name: Jerin Motors** Address: MD6M14CA4L4L00009 **Customer Complain:-**CH NO Full # Present Km 6392 Ak4LL4411690 V Engine has bad sound EN NO Full # **TVS King** Model # Deluxe plus 16.03.21 Sale Date # Date of Comp# 17.07.21 1St PS Date 1st PS Kms Date of Repair# N/A N/A pending Free service information 2nd Free Service **3rd Free Service 1St Free Service** Date **KMs** Date **KMs** Date **KMs** 08.04.20 891 21.05.20 2,981 30.06.20 4927 Observation:- we find and checked that engine has bad sounds Action Taken:- Please to be replace Gasket cylinder head, gasket cylinder block, Ball bearing 20\*42\*12 c3 6004,Ball bearing 6207R, Ball bearing 35\*72\*16 & gasket cover crank case R by new one under warranty. **Failure Particular** SL Part NO. Part Name Vendor code Approved Rejected Qty 339480 1 Ball Bearing 20\*42\*12 c3 6004 **Ball Bearing 6207R** 2 M7200530 1 3 G2200760 **Ball Bearing 35\*&2\*16** 1 4 G4010070 **Gasket cylinder Block** 1 M7010210 5 **Gasket cylinder Head** 1 6 G4030080 Gasket cover crank case-R Failure Parts Photo For Head Office Use **Head of Service Engineer DMS**

oms complete