Zone Name: Mymensingh

PRODUCT PERFORMANCE FEEDBACK REPORT

IFAD MOTORS LTD

DMS NO:

Head Office

IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208

Ref.No: Mym-28 F.R SING 28 Date: 31.12.20

Engineer Name:Md Jahid Hasa Mchanic Name:Md Rofiqul Islam Approved by: Prabir Biswas (Head of Service, Spare Parts & Production)

Customer Name: Md Shoel Mia(Dealer Jerin Motors) Mobile No: 01714766147 Address: Cecuya, Mymensingh Dealer Name: Jerin Motors Customer Complain: CH NO Full # MD6M14CL2K4P00053 Present Km Radiator fan not rotation EN NO Full # OL4PK4800363 TVS King Duramax Model # Sale Date # Not Sold Date of Comp# 30.12.20 1St PS Date 1st PS Kms Date of Repair# Rending N/A Free service information 1St Free Service 2nd Free Service 3rd Free Service Date **KMs** Date KMs Date **KMs**

Observation:- we checked and found that the radiator cooling fan not Motor not rotating. Fan Motor manufacturing

Action Taken:- Please to be replace the radiator fan by new one under warranty.

Failure Particular

SL	Part NO.	Part Name	Qty	Vandaraala		1
1	G4180820		Lecty	Vendor code	Approved	Rejected
2		The state of the s	+	4 2 2		•
3			+		-	
4						
		<u> La casa de la casa d</u>				

Failure Parts Photo

For Head Office Use Head of Service

Engineer

DMS