| | Ĺ | K | |
|-------|-------|----------|------------------------|
| Т | | | - |
| | ОТСІМ | AS LIMIT | 200 200 |
| | | | |
| : | R | ef.N | |
| | 16 | | TVS MOTORSLIMI Ref.N |

PRODUCT PERFORMANCE FEEDBACK REPORT



DMS NO: 3394



Head Office

IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208

 Ref.No:
 ppfr/01/dcm
 F.R SI NO#
 02
 Date:
 09.12.21

Zone Name: Chokoriya/Bashkhali Engineer Name: Md.Ruhul Mchanic Name: Abdul Momin

Approved by: Kaushik Sarker (Head of Service, Spare Parts & Production)

| Customer Name: Nobi Alom | | | Mobile No: | +8801885086978 | | | |
|--------------------------|----------------------|--------------------------|--------------------|----------------|--------------------|------------------|------------|
| Address: | Bohoddar gata, pekua | | | Dealer Name | Abu sama Motors | | |
| Customer Compl | ain:- | CH NO Full # | MD6M14CA2J4D02986 | | Present Kms # 4091 | | |
| Rear Shockabsor | ber oil | EN NO Full # | AK4DJ48 | 17824 | | Model # | Deluxe |
| leakage. | | Sale Date # | | | 26/03/2021 | Der | |
| | | Date of Comp# | | | 14/10/2021 | 1St PS Date | 1st PS Kms |
| | | Date of Repair# | | | 15/11/2021 | | |
| | | Free service information | | | | | |
| | | 1St Free Ser | rvice 2nd Free Ser | | e Service | 3rd Free Service | |
| | | Date | KMs | Date | KMs | Date | KMs |
| | | 29/04/2021 | 1025 | 25/7/21 | 4 091 | 28/09/2021 | 9752 |

Obserbation:- We checked & found that the rear shockabsorber inner tube oil seal cut & leakage.

Action Taken:-Require to replace this parts under warranty for your approval.

| | Failure Particular | | | | | | |
|----|--------------------|-------------------------|-----|-------------|----------|----------|--|
| SL | Part NO. | Part Name | Qty | Vendor code | Approved | Rejected | |
| 1 | G2090100 | Rear Shockabsorber Assy | 2 | | | | |
| 2 | | | ٠ | | | | |
| 3 | | | | | | | |
| 4 | | | | | | | |

| Failure Parts Photo | For Head Office Use | | | | |
|---------------------|---------------------|---|--|--|--|
| | Head of Service | Engineer | DMS | | |
| | 00/12/21 | Billal Hossain Dy Manager (Service) IFAD MOTORS LTD Head Office, Dhaka. | Milisha 9/12/2009 Orys Complete | | |