PRODUCT PERFORMANCE FEEDBACK REPORT

IFAD MOTORS LTD Head Office

DMS JOB NO 9857

3rd Free Service

Date

30.09.2020

KMs

5321

IFAD TOWER, 07 Tejgaon I/A, Dhaka-1208.

Ref.No:	Sylhet/Nov	/25/289	F.R SI NO)#	289	Date:	25.11.2020		
Zone Name:	Sylhet ,S	adar		Engineer Name:		Tisu Barua			
Approved by:	Prabir Bis	was, GM -Head of :	Service & Spare Parts	S.					
	Teels: 31	3		Ti	Mobile No:	01754505883			
Customar Name: Address:	Md.Ainul Haque Chatok, Sunamgonj.					Tawsis Motors			
Customar Co	<u> </u>	CH NO Full #	MD6M14CAXK4L00	126		Present Kms #	10,365		
Oil leakege from Front shock absorber		EN NO Full #	AK4LK4506688 08.07.2020	71		Model#	lpg		
		Sale Date # Date of Comp#	23.11.2020			1St PS Date	1st PS Kms		
		Date of Repair #	Pending	•••••		No	No		
		From convice information							

2nd Free Service

Date

29.08.2020

KMS

3562

Obserbation: We checked & found that oil leakege front shock absorbed

Action Taken:- Require to replace this parts under warranty for your approval.

Date

30.07.2020

1St Free Service

KMs

869

			Particular	A CONTRACTOR OF THE STATE OF TH	
SL	Part NO	Part Name	944	Vendor code	Rejected
1	-G4100180 −	From shock absorber	$\begin{pmatrix} 1 \end{pmatrix}$	Gabrial	
2	612100010	× I			 2000
3	,				
4					
5					
6				10 mg	

Failure Parts Photo

For Head Office Use



Monto as 26/11/2020 Drys Complete Stetusaher 28.11/10

25/01/2020.

TISU BARUA Service Engineer FAD MOTORS LTD Sylhet Sadar, Sylhet. Mob: 01704-113328