


PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD **Head Office**



3rd Free Service

KMs

Date

IFAD TOWER ,07 Tejgaon I/A, Dhako-1208.

Ref.No:	Habiga	Habiganj/sap/320		F.R SI NO#	320	Date:	15.09.2020		
Zone Name:	Habiganj Zone Er			ngineer Name:	: Md. Abdullah Al Zabed				
Approved by:	Prabir l	Biswas (Head of Se	rvice & Spar	e Parts)					
	,			V					
Customar Name:	MD. ABDUL GANI			Mobile No:	01317435232				
Address:	Bahubl	ıble, Habiganj			Dealer Name:	Shahjalal Automobile			
Customar Complain:- Cl		CH NO Full #	MD6M14C	A2J4A06916		Present Kms #	(2130)		
Front Shock absorber has		EN NO Full #	AK4AJ4413835			Model #	Tvs King Deluxe		
broken.		Sale Date #	18.07.2020	0		CNG/LPG			
		Date of Comp#	15.09.2020	0		1St PS Date	1st PS Kms		
a j		Date of Repair #	15.09.2020	0			8		
***		Free service information							

2nd Free Service

KMs

2130

Date

15.09.2020

12.08.2020 Obserbation:- we checked & found that front Shock absorber has broken.

Date

1St Free Service

KMs


860

Action Taken:- New one front shock absorber replaced.

Failure Particular								
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected		
1	G2100010	Front shock absorbe	1 pc	Gabrial (60000297) 27.11.17 H				
2		J						
3		/						
4				A SA	1			

Failure Parts Photo

For Head Office Use



crlibusaher 16.09.2020 5 complete