## PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 F.R SI NO# Date: 27.04.2021 278 Ref.No: April-278 Engineer Name: Md.Pabel Sarker Mchanic Name: Shimol Zone Name: Cumilla Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) 01728665982 Mobile No: Customer Name: Md.Shadat **Adunik Motors** Dealer Name: Burora, Cumilla Address: Present Km CH NO Full # MD6M14CL7L4M00027 **Customer Complain:-**TVS King Duramex EN NO Full # 0L4NL4500054 pressure gauge actually not right Model# Plus 07.03.2021 Sale Date # measured. Date of Comp# 26.04.2021 1St PS Date 1st PS Kms Date of Repair# Free service information 2nd Free Service **3rd Free Service 1St Free Service** Date KMs **Date** Date **KMs** 07.03.2021 985 Observation:we checked &found that pressure gauge actually not right measured. Action Taken:- Require to replace this parts under warranty for approval. Failure Particular Vendor code Approved Rejected SL Part NO. Part Name Qty G5141270 01 ressure gauge with sense 1 2 3 4 For Head Office Use **Failure Parts Photo Head of Service** DMS **Engineer**