

## PRODUCT PERFORMANCE FEEDBACK REPORT



## **IFAD MOTORS LTD**

## **Head Office**



IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208

Ref.No: F.R SI NO#- 321 Date: 25/2/2021

Zone Name: Chittagong (Chandrogona) Engineer Name: Md Farhad Hossen Mchanic Name: Rahman

Approved by: Prabir Biswas (Head of Service, Spare Parts & Production)

Received person - Eshan -017131503	355
------------------------------------	-----

	Received	persony Es	man -01/1315	00355		
Customer Name: Rokeya Begum	Mobile No:			01818225591		
Address: Ranghuniya				Dealer Name:	IML Lichubaga	n
Customer Complain:-	CH NO Full #	MD6M14C	A6K4K00136		Present Kms #	8040
Noise from Front shockabsorber	EN NO Full #	AK4KK4703311			Model #	Tvs King Deluxe
	Sale Date #	10-Aug-20				
	Date of Comp#	24-2-21			1St PS Date	1st PS Kms
	Date of Repair#	25-2-21	7			
	Free service information					
	1St Free Service		2nd	d Free Service	3rd Free Service	
	Date	KMs	Date	KMs	Date	KMs
	21/10/2020	1120	2/12/2021	4,704	10/2/2021	7560


Observation:- Front shockabsorber oil leakage and very hard.

Action Taken:- New one Front shockabsorber replace.

## Failure Particular

- Charlet and Charlet							
SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected	
1	G2100010	SHOCK ABSORBER ASSY FR	1	Badve			
2					***************************************		
3							
4							

Failure Parts Photo						
				Ţ		



**Head of Service** 

Engineer

For Head Office Use

or had a supplied to the suppl