

## PRODUCT PERFORMANCE FEEDBACK REPORT



## IFAD MOTORS LTD Head Office


DMS JOB NO 3342

Holding No:07, 1st Floor, IFAD Tower, Tejgaon Industrial Area, Dhaka-1208.

|   |                                 | Holding No.07, 13171     |                   |                            |              | Date:            | 8/10/2021                         |
|---|---------------------------------|--------------------------|-------------------|----------------------------|--------------|------------------|-----------------------------------|
| Ref.No:   | Ref.No: Faridpur /August-2021 / |                          |                   | F.R SI NO#                 |              |                  |                                   |
| Zone Name:  | Faridpur                        |                          |                   | Engineer/Mechanic Name: To |              | Tomai            | /                                 |
| Approved by: Prabir Biswas, Head of Service & Spare Parts                           |                                 |                          |                   |                            |              |                  |                                   |
|   |                                 |                          |                   |                            |              | <u> </u>         |                                   |
| Customar Name:  | ar Name: kalam chowkider        |                          |                   | Mobile No:                 |              | 01729360975      |                                   |
| Address:  |                                 | a,Shariatpur. Deale      |                   |                            | Dealer Name: | Howlader Motors  | FC20                              |
| Customar Complain:-   |                                 | CH NO Full #             | MD6M14LL5L4N00026 |                            |              | Present Kms #    | 5638                              |
| Water Pump fan brocken &  |                                 | EN NO Full #             | OL4NL4600188      |                            |              | Model #          | Tvs King Duramax<br>plus -225 LPG |
| pump leackage.  |                                 | Sale Date #              | 24.05.2021        |                            |              |                  | <b>F</b>                          |
|   |                                 | Date of Comp#            | 10.08.2021        |                            |              | 1St PS Date      | 1st PS Kms                        |
|   |                                 | Date of Repair #         | k                 |                            |              |                  |                                   |
|   |                                 | Free service information |                   |                            |              |                  |                                   |
|   |                                 | 1St Free Service         |                   | 2nd Free Service           |              | 3rd Free Service |                                   |
|   |                                 | Date                     | KMs               | Date                       | KMs          | Date             | KMs                               |
|   |                                 | 15.06.2021               | 1020              | 16.07.2021                 | 301/         | 10.08.2021       | 5638                              |
| Engineer Comment : We check & found that water pump leackage and pump fan brocken . |                                 |                          |                   |                            |              |                  |                                   |
| Engineer Comment: We check & found that water party                                 |                                 |                          |                   |                            |              |                  |                                   |
| I Warrant   |                                 |                          |                   |                            |              |                  |                                   |
| Action Taken:- Required this parts replcement under Warranty.                       |                                 |                          |                   |                            |              |                  |                                   |
|   |                                 | 4                        |                   |                            |              |                  |                                   |
|   |                                 |                          |                   | Epiluro Parti              | rular        | 1                | /                                 |

SL
Part NO
Part Name
Oty
Vendor code
Approved
Rejected

1
G4181310
WATER PUMP ASSY
1
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4
4</t



For Head Office Use

Slity Sahar pris Complete