PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: **Head Office** 3337 IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 Ref.No: Tan-75 F.R SI NO# 03.08.21 75 Date: Engineer Name: Md Jahid Hasan Mchanic Name: Md Rafigul Islam Zone Name: Tangail Approved by: Prabir Biswas (Head of Service, Spare Parts & Production) 1322158346 **Customer Name:** Abu bakkar Mobile No: Mama vagina engineering Address: Nagar jalfoi, Tangail Dealer Name: **Customer Complain:-**CH NO Full # MD6M14CL5K4P00046 Present Km 8201 Start problem & Radiator Fracture EN NO Full # OL4PK4000316 **TVS King Duramax** Model# Sale Date # 18.02.21 Date of Comp# 31.07.21 1St PS Date 1st PS Kms Date of Repair# Pending N/A Free service information **1St Free Service** 2nd Free Service 3rd Free Service Date Date **KMs Date KMs KMs** 23.03.2021 1013 02.05.21 3,872 24.06.21 6203 Observation:- we checked and found that the Radiator units Fracture & TCL unit weak. Action Taken:- Please to be replace this by new one under warranty. **Failure Particular** SL Part NO. Qty Part Name Vendor code Approved Rejected G4060400 1 TCI G4180820 2 **Fan Assy Radiator** 1 3 4 **Failure Parts Photo** For Head Office Use **Head of Service** Engineer **DMS**

ONS Complete