

PRODUCT PERFORMANCE FEEDBACK REPORT

IFAD MOTORS LTD **Head Office**

DMS JOB NO

89,Bir (Uttam C.R	Datta road,N	asir Trad	de center L	evel-12,Bang	lamotor ,Dh	aka.			
Ref.No:	Noakhali- Oct- 234			F.R SI NO#	234	Date:	07.10.20			
Zone Name: Feni-Noakhali.			Er	ngineer Name:	Kazi Samiul Hoque					
Approved by:	Prabir Bisv	vas, GM -Head of	Service & S	Spare Parts.			0			
*										
Customar Name:	Md yesin khan				Mobile No:	01878001812				
Address:	Hajigonj,ch	adpur Dealer Name:				Shikder enterprise				
Customar Con	nplain:-	CH NO Full #	MD6M14	CA9J4L08765		Present Kms #	2798			
Cut the ignition co	il	EN NO Full #	AK4LJ418	8219		Model#	Tvs King Deluxe			
		Sale Date #	16.07.20		7.	cng				
		Date of Comp#	07.10.20	. /		1St PS Date	1st PS Kms			
		Date of Repair #	07.10.20							
		Free service information								
		1St Free Ser	vice	2nd Fre	ee Service	3rd Free	Service			
		Date	KMs	Date	KMs	Date	KMs			
⇒		15.09.20	1105	Ø2.10.2020	2506					

Obserbation:- We checked & found that ignition coil failure


Not, 1.43316

Action Taken:- Please Replaced the following parts under warrants

Failure Particular									
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected			
1	G4060250	Ignition coil	1 1						
2		×							
3			3						
4			wa cas	11777					
. 5									
6									
				18 P 1					

Failure Parts Photo

For Head Office Use



Reading not usual beyond