T	VS	PRODUC	T PERFORM	ANCE	FEEDBA	CK REP	ORT	- > <	
							•		
мот	MOTORS LATED IFAD MOTORS LTD							DMS NO:	
		IFAD T	Head Office lot-7(New), Tejgoan Industrial Area, Dhak					9208	
		IFAD Tower, P	lot-7(New), Te	jgoan	Industrial A	Area, Dha	ka-1208		
Ref.No: Habiganj/Mra/347					F.R SI NO#		Date:	08.03.2021	
Zone Name: Habiganj Zone			Engineer Name Al Zabed			e: Md. Abdulla	h Mchanic Nar	me: Md. Shipon Alom	
Appro	ved by:	Prabir Biswas (Head o	of Service,Spare Pa	rts & Pr	oduction)				
ustomer N	-								
	vame:	Mst: Peyara Khatun	Mobile No				01707133	: 01707133370	
Address: Bahubole, Habiganj			Dealer Nar				Shahjalal Automobile		
Customer Complain:-			CH NO Full # MD6M14CA9J4A079			48	Present Kr		
ont Shock absorber has been broken.			EN NO Full #	AK4AJ4823087			Model #	Tvs King Deluxe	
			Sale Date #	14.12.2			wodel#	CNG/LPG	
			Date of Comp# Date of Repair#	04.03.2	And the second s		1St PS Date	1st PS Kms	
			Date of Repair#	04.03.2					
			Free service inform  1St Free Service 2nd Free Service				T		
			Date	KMs	Date	KMs		Free Service	
			25.01.2021	1210	04 03 2021	5,250	Date	KMs	
oservation	1:- We c	hecked & found that f	ront Shock absorb	er has b	een broken	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		L	
			Failure	e Particu	ular		0 12		
SL .		Part NO.	Part Name		Qty	ty Vendor coc Appro		Daissa I I	
.						G0000297	Approved	Rejected	
1		G4100180	Front shock absorbe		01	G2100010			
ton,	G21	00010 · Am	AND III		11_	02/2/17H			
3	<u>ज</u> ू र	00010 - 141 (			V			1.	
								1	
	.~				2		-/		
F	ailure P	arts Photo	For Head Office Use						
1,20			Head of Service						
						Engineer		DMS	
			16/3/2021					, ,5	
								1/2 ~	
	12	The second second	\\	$\gamma \gamma /$	1		10	De Car	
			/m/ 0/201/			Modor		(h) s	
	14		1/11	(n ()		JHK	m/2	En Con	
12			1/1	101		00	6,,	The say	
3.5			16	1				$\bigcap_{\mathcal{A}}$	
45							*		
		# 30 miles ( ) and ( )			1				