



PRODUCT PERFORMANCE FEEDBACK REPORT





IFAD MOTORS LTD Head Office

DMS JOB NO 2805

7-Tejgoan Industrial Area, Ifad Tower, Level-01, Dhaka-1208.

Ref.No:	Noakhali- nov- 237	F.R SI NO#	237	Date:	10.11.20
	Feni-Noakhali.	Eng	gineer Name:	Kazi Samiul Hoque	
Appleared by	Probin Ricurae GM -Head of	Service & Spare Parts			

Approved by: Prabir Biswas, GM -Head of Service & Spare Parts

Customar Name:	Md habib	ur rahaman			Mobile No:	01318821280		
Address:	Kaliyapar	a,chadpur.		W	Dealer Name:	Bhuiya mote	ors	
Customar Co		CH NO Full #	MD6M1	4CA9K4K001	.94	Present Kms #	(5844	
Rear shockabsorber oil leakage		EN NO Full #	AK4KK41	L04831		Model # Tvs King D		
		Sale Date #	29.06.20			Wodel #	cng	
		Date of Comp#	09.11.20		26.2	1St PS Date	1st PS Kms	
×		Date of Repair #		ć.				
		Free service information						
		1St Free Ser	1St Free Service 2nd F		Free Service 3rd F		ee Service	
4		Date	KMs	Date	KMs	Date	KIVIs	
		16.08.20	988	18.09.20	2644	21.10.20	4933	

Obserbation:- We checked & found that rear shockabsorber oil leakage.

Action Taken:- Please Replaced the following parts under warranty

Failure Particular						
SL	Part NO	Part Name	Qty		Approved	Rejected
1	G2090100	Rear shockabsorber	(1)	Gabrial	20	
2	\$	N		ing consent consent on		
3			2.18	A to all all place to the second of		
4	2			- Complete of	D 14 . 1	
5				es de commune e sur regionalme de M.C.		
6				, South Kathaganda si	ecker co	1.

Failure Parts Photo

For Head Office Use

1871/2020

Drys Complete

10. U. 20

14/11/0020

/2020

9839